







SCHEMATIC WIRING DIAGRAM - 3 PHASE  
INTERNAL OVERLOAD (LINE BREAK) AND  
CRANKCASE HEATER. REF DWG MD472-43



SCHEMATIC WIRING DIAGRAM - 3 PHASE  
INTERNAL OVERLOAD (LINE BREAK) AND CRANKCASE HEATER.

WARNING-WIRING DIAGRAM MUST BE FOLLOWED  
AS SHOWN. ANY MISWIRING CAN CAUSE SERIOUS  
ELECTRICAL HAZARD AND POTENTIAL DAMAGE OR  
RUPTURE OF COMPONENT ELECTRICAL PARTS.

AG - 3 PHASE - INTERNAL OVERLOAD (LINE BREAK)- CRANKCASE HEATER.

ENGLISH

Q. A. SYMBOLS

☆ = CATEGORY I  
 △ = CATEGORY II  
 □ = CATEGORY III  
 = CATEGORY IV

[illegible]