PART NO. DEAH-3

Ⓒ

WARNING-WIRING DIAGRAM MUST BE FOLLOWED AS SHOWN. ANY MISWIRING CAN CAUSE SERIOUS ELECTRICAL HAZARD AND POTENTIAL DAMAGE OR RUPTURE OF COMPONENT ELECTRICAL PARTS.



Ⓙ SCHEMATIC WIRING DIAGRAM-3 PHASE-INTERNAL OVERLOAD (LINE BREAK)

REF. DWG. MD472-24

NOTE!

1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.

AH-3 PHASE-INTERNAL OVERLOAD (LINE BREAK)

AH

LT	LC	CHANGE	DATE
L	5F 6F	235648 ADDED NOTE	WFMF 7-11-97
K	5E 3E RE	#208830 ADDED 4,12 & 13-RE 6,RIS IN WEMS	RPL 2-25-83
J	7C	#208793 DESCRIPTION REVISED	RPL 2-3-83
H	4C	#204234 TERMINAL COVER	HMM
G	3C	WAS TERMINAL COVER	6-13-80
F	1C	TERMINAL COVER	
E	6D	#204079 CONTACTS REVISED	JMC 5-7-80
D	-	#201045 REVISED	HMM 10-17-78
C	7E	NOTE ADDED #199452	COWEN 7-1-77
B	-	REDRAWN PICTURE ROTATED 90° #194820	COWEN 8-28-75

THIS DRAWING OR PRINT (I) IS THE PROPERTY OF TECUMSEH PRODUCTS COMPANY (TECUMSEH) AND CONTAINS PROPRIETARY INFORMATION AND INFORMATION BELONGING TO TECUMSEH. (II) IS LOANED FOR A SPECIFIC PURPOSE ON THE EXPRESS AND SPECIFIC CONDITION THAT NEITHER IT NOR THE INFORMATION CONTAINED THEREIN OR DISCLOSED THEREIN SHALL BE DISCLOSED OR OTHERWISE MADE AVAILABLE TO OTHERS WITHOUT THE EXPRESS AND SPECIFIC WRITTEN CONSENT OF TECUMSEH AND THAT SUCH INFORMATION SHALL BE USED ONLY AS EXPRESSLY AND SPECIFICALLY AUTHORIZED IN WRITING BY TECUMSEH AND NOT OTHERWISE. (III) SHALL NOT BE COPIED OR DUPLICATED IN WHOLE OR IN PART TO THE EXTENT WITHOUT TECUMSEH'S PRIOR WRITTEN CONSENT THERETO, UNLESS SUCH COPY OR DUPLICATE IS SENT AND (IV) SHALL BE RETURNED TO THE RECIPIENT THEREOF UPON THE RECIPIENT'S WRITTEN REQUEST PROMPTLY AFTER SUCH REQUEST IS MADE.

DIS. CODE 3482

DO NOT SCALE THIS DRAWING

ALL FERROUS MATERIALS MUST BE CLEANED, PHOSPHATIZED, OR AT COMPRESSOR ASSEMBLY.

NAME: ELECTRICAL HOOKUP

DWN. R. COWEN 8-28-75 | CK. | APR. | SCALE

TECUMSEH, MICHIGAN

MATERIAL

THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO

PART NO. DEAH-3

BRUNING 44-511 A 24734