



115 OR 230 VOLT - SCHEMATIC WIRING DIAGRAM
CSR OR CSR START CAPACITOR ASSIST



WIRING DIAGRAM MUST BE FOLLOWED AS SHOWN. ANY MISWIRING
CAN CAUSE SERIOUS ELECTRICAL HAZARD AND POTENTIAL DAMAGE
OR RUPTURE OF COMPONENT ELECTRICAL PARTS.



RK

Q.A. SYMBOLS

[illegible]