

8

7

6

5

4



3

2



1

DRAWING NO.

DEAG02



SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD (LINE BREAK) AND
CRANKCASE HEATER. REF DWG MD472-43



SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD (LINE BREAK) AND CRANKCASE HEATER.

WARNING-WIRING DIAGRAM MUST BE FOLLOWED
AS SHOWN. ANY MISWIRING CAN CAUSE SERIOUS
ELECTRICAL HAZARD AND POTENTIAL DAMAGE OR
RUPTURE OF COMPONENT ELECTRICAL PARTS.

AG - 3 PHASE - INTERNAL OVERLOAD (LINE BREAK)- CRANKCASE HEATER.

ENGLISH	
Q.A. SYMBOLS	
☆ = CATEGORY I	
△ = CATEGORY II	
□ = CATEGORY III	
○ = CATEGORY IV	

AG

					I	DATE	THIS DRAWING OR PRINT IS THE PROPERTY OF TECUMSEH PRODUCTS CO. AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF TECUMSEH PRODUCTS CO. ANY SUCH VIOLATION SHALL BE SUBJECT TO THE FULL AND COMPLETE LIABILITY OF THE USER.										DIS. CODE		NAME										ELECTRICAL HOOK-UP										THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO											
#240574-089					—	CHANGE	REDRAWN ON UNIGRAPHICS AND UPDATED WITH MD472-43										OWN. EAC 17MAR05		CK		TECUMSEH PRODUCTS CO.										TECUMSEH, MICHIGAN										DRAWING NO.									
					I	LC											MATERIAL		N/A		DEAG02																													
					T	LC											DRAWING No.		MD888-08		REVISION LEVEL:		REL																											