


WARNING-WIRING DIAGRAM MUST BE FOLLOWED AS SHOWN. ANY MISWIRING CAN CAUSE SERIOUS ELECTRICAL HAZARD AND POTENTIAL DAMAGE OR RUPTURE OF COMPONENT ELECTRICAL PARTS.



230 V. SCHEMATIC WIRING DIAGRAM -CSIR- CURRENT RELAY
-INTERNAL OVERLOAD PROTECTOR WITH START WINDING
HEATER (LINE BREAK)
(REF. DWG. MD 472-80)

AH-230 V.-CSIR-CURRENT RELAY-INTERNAL OVERLOAD
PROTECTOR WITH START WINDING HEATER (LINE BREAK)

NOTE :

1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.

Q.A. SYMBOLS

SUS 4/15/97		DATE	DIS. CODE 34\$21		NAME ELECTRICAL HOOK-UP	
#235648 ADDED NOTE	REL #227462	CHANGE	SCALE 1=1		THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO	
5F	LT LC	TECUMSEH PRODUCTS CO. TECUMSEH, MICHIGAN				PART NO. DEAH-7
A	MATERIAL					INTERNAL USE ONLY U8101SK67(SHERMAN)AH-DEAH07C1A-C.PRT