





1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.
2. IDENTIFIED CONDUCTOR MAYBE WHITE OR RIBBED (115 VOLT ONLY-NEUTRAL).
3. IF TWO RUN CAPACITORS ARE REQUIRED HOOK-UP AS SHOWN.

1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.
2. IDENTIFIED CONDUCTOR MAY BE WHITE OR RIBBED (115 VOLT ONLY-NEUTRAL).
3. IF TWO RUN CAPACITORS ARE REQUIRED HOOK-UP AS SHOWN.

WARNING-WIRING DIAGRAM MUST BE FOLLOWED  
AS SHOWN. ANY MISWIRING CAN CAUSE SERIOUS  
ELECTRICAL HAZARD AND POTENTIAL DAMAGE  
OR RUPTURE OF COMPONENT ELECTRICAL PARTS.




115 OR 230 VOLT - SCHEMATIC WIRING DIAGRAM - PSC.  
(REF. DWG. MD472-4)

AK-115 OR 230 V.-PCS.  
AK-115 OR 230 V.-CSR OR CSR START CAPACITOR ASSIST.

3D, VNX8 | B

ENGLISH



|              |
|--------------|
| Q.A. SYMBOLS |
|--------------|

☆ = CATEGORY I  
 ▲ = CATEGORY I  
 ■ = CATEGORY I  
 = CATEGORY I

A4

[illegible]