


--NOTES--




1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.
2. IF TWO CAPACITORS ARE REQUIRED HOOKUP AS SHOWN.



--NOTES--

1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.
2. IF TWO RUN CAPACITORS ARE REQUIRED HOOKUP AS SHOWN.

WARNING - WIRING DIAGRAM MUST BE FOLLOWED AS SHOWN. ANY MISWIRING CAN CAUSE SERIOUS ELECTRICAL HAZARD AND POTENTIAL DAMAGE OR RUPTURE OF COMPONENT ELECTRICAL PARTS.



230 VOLT-SCHEMATIC WIRING DIAGRAM-PSC-INTERNAL OVERLOAD (LINE BREAK)-START WINDING HEATER

REF. DWG. MD472-33

AW-230 V.-PSC-INTERNAL OVERLOAD(LINE BREAK)-START WINDING HEATER
AW-230 V.-CSR OR CSR START CAPACITOR ASSIST-INTERNAL OVERLOAD (LINE BREAK)-START WINDING HEATER

Q.A. SYMBOLS

AW

230 VOLT SCHEMATIC WIRING DIAGRAM-CSR OR CSR START CAPACITOR ASSIST-INTERNAL OVERLOAD (LINE BREAK)-START WINDING HEATER

REF. DWG. MD472-34

DATE	CHANGE	BY	REASON	DIS. CODE	NAME	SCALE	THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO	PART NO.
4/16/97	1	SJS	ADDED NOTE	3482	ELECTRICAL HOOKUP	1"=1"		DEAW1
01/30/97	2	HINMAN	REDRAWN NO CHANGE					
07/30/97	3	CHANCE	ADDED NOTE					
07/30/97	4	CHANCE	ADDED NOTE					
07/30/97	5	CHANCE	ADDED NOTE					
07/30/97	6	CHANCE	ADDED NOTE					
07/30/97	7	CHANCE	ADDED NOTE					
07/30/97	8	CHANCE	ADDED NOTE					
07/30/97	9	CHANCE	ADDED NOTE					
07/30/97	10	CHANCE	ADDED NOTE					
07/30/97	11	CHANCE	ADDED NOTE					
07/30/97	12	CHANCE	ADDED NOTE					
07/30/97	13	CHANCE	ADDED NOTE					
07/30/97	14	CHANCE	ADDED NOTE					
07/30/97	15	CHANCE	ADDED NOTE					
07/30/97	16	CHANCE	ADDED NOTE					
07/30/97	17	CHANCE	ADDED NOTE					
07/30/97	18	CHANCE	ADDED NOTE					
07/30/97	19	CHANCE	ADDED NOTE					
07/30/97	20	CHANCE	ADDED NOTE					