







NOTE:

1. SEE BILL OF MATERIAL FOR PART NUMBERS.



SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD (LINE BREAK)
REF DWG MD472-24

SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD AND (LINE BREAK)
REF DWG MD472-43



SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD (LINE BREAK)
REF DWG MD472-24

SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD (LINE BREAK) AND
CRANKCASE HEATER. REF DWG MD472-43

VS - 3 PHASE - INTERNAL OVERLOAD (LINE BREAK) - CRANKCASE WATER.
VS - 3 PHASE - INTERNAL OVERLOAD (LINE BREAK).

ENGLISH 	Q.A. SYMBOLS ☆ = CATEGORY I △ = CATEGORY II □ = CATEGORY III = CATEGORY IV
--	---

[illegible]