


PART NO.
MD472-1



115 OR 230 V SCHEMATIC WIRING DIAGRAM - CSIR

AE
TP

Q.A. SYMBOLS

	--	DATE	DIS. CODE	NAME SCHEMATIC WIRING DIAGRAM	
	#237130-001 REDRAWN NO CHANGE	CHANGE	DWN. HINMAN 08-29-98	THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO	
	L --	LC		PART NO. MD472-1	
	LT	<p>THIS DRAWING OR PRINT (1) IS THE PROPERTY OF TECUMSEH PRODUCTS COMPANY. TECUMSEH AND CONTAINS PROPRIETARY AND CONFIDENTIAL INFORMATION BELONGING TO TECUMSEH. (1) IS MADE AVAILABLE TO THE RECIPIENT ON THE EXPRESS AND SPECIFIC CONDITION THAT NEITHER IT NOR THE INFORMATION CONTAINED THEREON OR DISCLOSED THEREIN SHALL BE DISCLOSED OR MADE AVAILABLE TO OTHERS WITHOUT THE EXPRESS AND SPECIFIC WRITTEN CONSENT OF TECUMSEH AND THAT SUCH INFORMATION ONLY AS EXPRESSLY AND SPECIFICALLY APPROVED IN WRITING BY TECUMSEH AND NOT OTHERWISE. (1) SHALL NOT BE COPIED OR DUPLICATED IN ANY MANNER OR PRINTED, EXTENDED, WITHOUT TECUMSEH'S WRITTEN CONSENT AND SHALL BE RETURNED BY THE RECIPIENT THEREOF TO TECUMSEH AT THE LATTER'S REQUEST PROMPTLY AFTER SUCH REQUEST IS MADE.</p>	DO NOT SCALE THIS DRAWING ALL FERROUS MATERIALS MUST NOT BE MAGNETIZED AS RECEIVED OR AT COMPRESSOR ASSEMBLY.		
				MATERIAL INTERNAL USE ONLY p:\hinman\ae\ae-md472-01-1-a.prt	