



1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.
2. IDENTIFIED CONDUCTOR MAYBE WHITE OR RIBBED (115 VOLT ONLY-NEUTRAL).
3. IF TWO RUN CAPACITORS ARE REQUIRED HOOK-UP AS SHOWN.

1. ASSEMBLE PARTS AS SHOWN IF SPECIFIED ON B/M.
2. IDENTIFIED CONDUCTOR MAY BE WHITE OR RIBBED (115 VOLT ONLY-NEUTRAL).
3. IF TWO RUN CAPACITORS ARE REQUIRED HOOK-UP AS SHOWN.

115 OR 230 VOLT-SCHEMATIC WIRING DIAGRAM
CSR OR CSR START CAPACITOR ASSIST
(REF.DWG. MD472-35)

115 OR 230 VOLT - SCHEMATIC WIRING DIAGRAM - PSC.
(REF. DWG. MD472-4)

3D, VNXB

ENGLISH

Q.A. SYMBOLS

★ = CATEGORY I
 ▲ = CATEGORY II
 ■ = CATEGORY III
 ○ = CATEGORY IV

[illegible]