







SCHEMATIC WIRING DIAGRAM - 3 PHASE
INTERNAL OVERLOAD (LINE BREAK) CRANKCASE HEATER.
REF. DWG. MD472-43



COMPRESSOR UNIT GROUND (SCREW IS NOT PROVIDED BY T.P. CO.)

WARNING-WIRING DIAGRAM MUST BE FOLLOWED AS SHOWN, ANY MISWIRING CAN CAUSE SERIOUS ELECTRICAL HAZARD AND POTENTIAL DAMAGE OR RUPTURE OF COMPONENT ELECTRICAL PARTS.

AV-3 PHASE-INTERNAL OVERLOAD (LINE BREAK)-
CRANKCASE HEATER.

Q.A. SYMBOLS

AV

DIS. CODE				NAME		SCALE		THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO	
34524				ELECTRICAL HOOK-UP		1" = 1"			
				TECUMSEH PRODUCTS CO.		TECUMSEH, MICHIGAN		PART NO.	
				MATERIAL				DEAV-4	
				INTERNAL USE ONLY		UGIDISK51(SHERMAN)AV-DEAV04C18-C.PRT			