






230 VOLT - SCHEMATIC WIRING DIAGRAM - CSR OR CSR START CAPACITOR ASSIST
INTERNAL OVERLOAD (LINE BREAK) - CRANKCASE HEATER REF. DWG. MD472-66



230 VOLT - SCHEMATIC WIRING DIAGRAM - PSC - INTERNAL OVERLOAD (LINE BREAK) -
CRANKCASE HEATER.

Q.A. SYMBOLS					
AW - 230V - PSC - INTERNAL OVERLOAD (LINE BREAK) - CRANKCASE HEATER					
AW - 230V - CSR OR CSR START CAPACITOR ASSIST - INTERNAL OVERLOAD (LINE BREAK) - CRANKCASE HEATER					
AW					
ELECTRICAL HOOK-UP					
SCALE 1"=1"					
THIS PRINT SUPERSEDES ALL PRINTS PRIOR TO					
TECUMSEH PRODUCTS CO. TECUMSEH, MICHIGAN					
MATERIAL					
INTERNAL USE ONLY UGIDISK6(SHERMAN)AW-DEAW05CB-C-PR					
DEAW-5					